

O : Parts Location

Code	See Page	Code	See Page	Code	See Page
C8	36	J2	37		

: Junction Block and Wire Harness Connector

Code	See Page	Junction Block and Wire Harness (Connector Location)	
IF	25	Instrument Panel Wire and Instrument Panel J/B (Lower Finish Panel)	
3A	29	Instrument Panel Wire and RH J/B (Right Side of the Instrument Panel Reinforcement)	

∇

: Ground Points

Code	See Page	Ground Points Location
IE	42	Behind Combination Meter